Work Order ID 57820

April 16, 2010 10:41:45 AM

Item ID:

D3909-5

Revision ID:

Item Name:

Eyebolt Stud

Start Date:

Start Qty: 6.00 16/04/2010

Required Date: 29/04/2010 Req'd Qty: 6.00

Operation

Description

Reference:

Approvals:

Process Plan:

QC:

Date:

Date:

Tooling:

Accept

SPC (Y/N):

Set Up/ **Run Hours** Draw Number

Cust Item ID:

Customer:

Draw Rev.

Date:

Date:

Plan Code Accept Qty

Reject Qty

Run

Setup Start

Stop

Start

Stop

Reject Number Stamp

Insp.

Work Center ID Draw Nbr

Sequence ID/

Revision Nbr

D3909

В

100

Doosan

Doosan Lathe

Memo

turn as per dwg and folio FA872

DWG REV: FOLIO REV:

0.00

0.00

DEBURR

110

Quality Control

QC2- Inspect parts off machine FAI/FAIB

10/04/17

Memo

0.00

0.00



Remember....

- Lean is war to WASTE.
- Waste is an activity or output that adds cost but does not add value
- You have to get into a mindset of identifying and eliminating all wastes.

The 7 deadly wastes

- 1. Overproduction
- 3. Transportation
- 5. Unnecessary Inventory
- 7. Unnecessary Motions

- 2. Rework
- 4. Inappropriate / over Processing
- 6. Delays / Waiting

Work Order ID 57820

April 16, 2010 10:41:45 AM

Item ID:

D3909-5

Revision ID:

Item Name:

Eyebolt Stud

Start Date:

16/04/2010 **Required Date: 29/04/2010**

Start Qty: 6.00

Rea'd Otv: 6.00

Reference:

Approvals:

Process Plan:

OC:

Date:

Date:

Ouality Control

Accept



Setup Start

Stop



Cust Item ID:

Customer:

Start



Stop

Sequence ID/ **Work Center ID**

120

Operation Description

QC8- Inspect parts - second check

Memo

Set Up/ **Run Hours**

0.00

Tooling:

SPC (Y/N):

0.00

Draw Number

Plan Code

Accept **Qty**

Reject Qty

Run

Reject Number

Insp. Stamp

BT 10/04/14

Date:

Date:

Draw

Rev.

150

Packaging

Packaging

Identify as per dwg & Stock Location:

Memo

0.00

/h/1/20 6

160

Quality Control


OC21- Final Inspection - Work Order Release

0.00

Memo

0.00

10/04/20X) MF 10-4-20



tean Training Event

Picklist Print

April 16, 2010 10:41:44 AM

Work Order ID: 57820

Parent Item:

D3909-5

Parent Item Name: Eyebolt Stud

Comments:

IPP REV:A NEW ISSUE 09-11-25 JLM VERIFIED BY:DD



Start Date: 16/04/2010

Required Date: 29/04/2010

Start Qty: 6.00

Required Qty: 6.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Bin Primary Item Location

Last Location

Route Seq ID

Qty on Unit of Measure Hand

Remaining Qty To Pick

Qty Issued Date Status Issued

M303R1.000

Purchased

No

100

45.2000

1.5789

303 Round Bar 1.00

Warehouse	Loc Oty	Loc Code
Location		
Main Warehouse		
MAT028	45.2	
113325	45.2	

1.6 JL 10/04/17

DART AEROSPACE LTD	Work Order: 57820
Description: EVEN H Stud	Part Number: \\\\3909-S
Inspection Dwg: \3909 Rev: \B	Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

, .		X	First Artic	le	Proto	type	
Drawing Dimension	Tolerance		Actual Dimension	Accept	Reject	Method of Inspection	Comments
0-129	+.00S		.129	2			
1.38	1.		1.385				
. HOO	+0 +0 -010 +-010		396				
.700	+-010 -0		-702	V			
1.030	+ - w/w 010		130				
.375	-020		. 368				
700	010		-700	/			
.250	+.010		250				4
1.30	+ 030		1.299	/			
5-06	±-030		.060				
2.68	±-030		2.682				
-310	±-010		.3//	V			
-750	010		.750	V			
-375 (ptch)	+-010		.375				
1.00	±.030		1.00				
-75	+-030 +-010		-750				
.735	T-0(0 -0		.740				
				, , , , , , , , , , , , , , , , , , , ,			

Measured by:	Audited by:	Prototype Approval:	N/A
Date: 10/04/17	Date: 10/04/17	Date:	N/A

Rev	Date	Change		Revised by	Approved
Α		New Issue	-	KJ/JLM	

